Staggered Inspection Process **CFA START** Ask the hard copy of the pulling test report and the specimen from the QC TL if the running style has snap buttons/rivets/eyelets/grommets/tie cords/sew on buttons. Conduct an odor test, water absorbency test (if needed), and moisture test (Follow Moisture Test Process) per P.O and record the result in the packing guide. Get a minimum of 3 pieces of garments for quality inspection from the closed carton that has a stamp of EOL QC and packer at the upper long flap of the carton. Conduct inspection following the 5 steps on how to inspect the garments and record the result in the CFA Inspection Report. PASSED— RESULT **FAILED** Escalate the rejection to Line Stamp in the upper right Leader, End of Line QC, QC TL, side of the carton, near and QC Supervisor to solve the the zebra sticker, CMP issue until it report per carton #, and will pass and let them affix their signature in the CFA Inspection let the QC TL/Supervisor sign in report, and re-inspect the the Inspection report. garments from the opened cartons. **END**

Final Inspection Process CFA START Ask a hard copy of pulling test result from the QC TL if the running style has snap buttons/rivets/eyelets/grommets/ tie cords/sew-on buttons and the FGWT result from the End of Line QC and put remarks (passed/failed/no result) in the CFA Summary of Final Inspection Report. Conduct inspection based on AQL 1.0 level 1 for International and level 2 for Japan. Record the result in the CFA Summary of Final Inspection report. RESULT PASSED. FAILED-Escalate the rejection to Line Stamp in the upper Leader, End of Line QC, QC right side of the carton, TL, and QC Supervisor to near the zebra sticker. solve the issue until it CMP report per carton will pass and let them affix #, and let the their signature in the CFA QC TL/Supervisor sign Inspection report, and rein the Inspection inspect the garments from the report. opened cartons. **END**

Encoding and Keeping of CFA Inspection Report Process

